

#whdentalwerk
f @ in ▶
wh.com

User Maintenance
Lexa MN-111



Replace the door gasket
🛒 Ref. **F460535X**



Perform monthly maintenance

○ Cycles
📅 Months



Replace the HEPA filter
🛒 Ref. **W322400X**

lexa



Scan the QR code with your mobile phone for **FAQ VIDEOS** on Lisa





W&H Sterilization Srl.

Via Bolgara, 2

24060 Brusaporto (BG), Italy

t +39 035-66 63 000

f +39 035-50 96 988

office.sterilization@wh.com

wh.com

med.wh.com



Dent

Med